

Condition Report

Completed by Alliance Inspection Management



2020 Ford Transit Cargo Van

Vin: 1FTBR2X88LKB73702



Vehicle Information

Year : 2020
Brand : Ford
Model : Transit Cargo Van
Series :
Body Type : Van
Drive Type : AWD
Engine : 6
Transmission : A/T
Mileage : 171069
Exterior Color : Black
Trim Color : Black
Trim Type : Leatherette

Inspection Details

Inspection Date : 19-Apr-2024 1:17 pm
Inspection ID : 2463664
Inspector : 8758

Inspection Notes :

Vehicle Accessories

Audio/Video

- AM/FM Stereo

Convenience Exterior

- Third Passenger Door
- Tow Hooks

Convenience Interior

- Adjustable Steering Wheel

Equipment

- A/C

Glass/Wipers/Lamps

- Intermittent Wipers

Pwr Grp

- Power Door Locks
- Power Steering
- Power Windows

Safety

- Brake Assist
- Driver Air Bag
- Passenger Air Bag
- Rear Parking Aid
- Tire Pressure Monitor
- Traction Control

Seating

- Bucket Seats
- Vinyl Seats

Wheels

- ABS
- Steel Wheels
- Tires - Front All-Season
- Tires - Rear All-Season

Added Value

- MP3 Player

Tire Information

	Manufacturer	Size	Depth		Manufacturer	Size	Depth
Left Front	Goodyear	235/65-16	8/32	Right Front	Goodyear	235/65-16	8/32
Left Rear	Goodyear	235/65-16	6/32	Right Rear	Goodyear	235/65-16	5/32
Spare	Goodyear	235/65-16	12/32				

*Tire Depth of 4/32 or greater is considered normal

Condition Report

Completed by Alliance Inspection Management



2020 Ford Transit Cargo Van

Vin: 1FTBR2X88LKB73702

Vehicle Condition

Wear and Tear

1	Hood	Dent/No Paint Dmg	1/2" to 1"
2	LF Fender	Dent/Paint Dmg	1/2" to 1"
3	LF Door	Dent/Paint Dmg	1" to 2"
4	LT Qtr Panel	Mult Dents/No Paint Dmg	10 or More
5	LT Qtr Panel	Scratch Heavy	2" to 3"
6	LR Cargo Door	Mult Dents/No Paint Dmg	4
7	RR Cargo Door	Mult Dents/No Paint Dmg	3
8	RR Bumper Extension	Broken	Replacement Required
9	RT Qtr Panel	Dent/Paint Dmg	GR 12"
10	RR Door	Dent/Paint Dmg	GR 12"



2020 Ford Transit Cargo Van
Vin: 1FTBR2X88LKB73702

Vehicle Condition Questions

Smoker Car?	N	Service Light On?	N
VIN Plate Damaged?	N	Odometer Tampered?	N
Correct Emission Sticker?	Y	Driveable	Y
Roof Type	Hard Top	Odometer Type	Digital
Odometer Digits	6	Odometer Operable	Y
Emissions	50 St Emis	Combo	2
Infrared	0	Keyless Go	0
Master	0	Remote/Fob	0
Spare	0	Trunk	0
Valet	0		

Date : 19-Apr-2024

Signature :

Condition Report

Completed by Alliance Inspection Management

2020 Ford Transit Cargo Van

Vin: 1FTBR2X88LKB73702

Vehicle Pictures


Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Cargo Area**



Picture Description : **Other**



Condition Report

Completed by Alliance Inspection Management

2020 Ford Transit Cargo Van

Vin: 1FTBR2X88LK873702

Picture Description : **Front Interior**



Picture Description : **Dashboard**




Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Vin/Id Manufacturer Label**



Picture Description : **Wheel**



Condition Report

Completed by Alliance Inspection Management

2020 Ford Transit Cargo Van

Vin: 1FTBR2X88LKB73702

Picture Description : **Other**




Picture Description : **Odometer**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Right Rear Corner**



Picture Description : **Left Front Corner**



Condition Report

Completed by Alliance Inspection Management



2020 Ford Transit Cargo Van

Vin: 1FTBR2X88LKB73702

Picture Description : **Other**



Picture Description : **Other**



Condition Report

Completed by Alliance Inspection Management



2020 Ford Transit Cargo Van

Vin: 1FTBR2X88LKB73702

Damage Pictures

Picture Description : **Bumper Extension Broken Replacement Required**



Picture Description : **Qtr Panel Mult Dents/No Paint Dmg 10 or More**



Picture Description : **Door Dent/Paint Dmg GR 12"**



Picture Description : **Qtr Panel Dent/Paint Dmg GR 12"**

